

Replacement UV lamps for Oce printers



Oce (Cannon Solutions America) Arizona series printers are extremely versatile and among the most popular flatbed printers. They offer high quality and robust design. TCS Technologies manufactures American-quality, second-source UV curing lamps for all Oce printers. We offer a cost-effective alternative to Oce -- Cannon OEM product.

There are three different styles of UV curing lamps used by Oce. Older and entry-level machines (Arizona 200/250/300/350) use a cassette style lamp. Examples include Oce part number 3010105468, 29701413 and Subzero 085H.



Higher production machines (Arizona 318 GL, 360 GT, 440/460/480 GT & XT & 550 GT & XT, 640/660 GT & XT) use higher power lamps with round black connectors. These are easy to replace and offer longer life. Examples include Oce part numbers 3010111622, 3010111639, 3010109531 and 3010109681.



Here is an example of the "round style" UV lamp connector

Oce's newest generation printers (Arizona 1200 series GT & XT, 2200 series GT & XT and 6100 series) use a rectangular black UV lamp connector. Examples include part number 3010117500 & 3010117501. Here is a picture of a typical rectangular UV lamp connector.



TCS Technologies manufactures reliable substitute for OCE OEM bulbs. If you are looking for a second source bulb, why risk installing something from the Far East when a USA product is available for comparable cost

We manufacture UV curing lamps for the following Oce printers:

Arizona 200 GT	ArizonaT220UV	Arizona 250 GT
Arizona 300GT	Arizona 318 GL	Arizona 318 GT
Arizona 350 GT	Arizona 360 GT	Arizona 440 GT
Arizona 440 XT	Arizona 460 GT	Arizona 460 XT
Arizona 480 GT	Arizona 550 GT	Arizona 550 XT
Arizona 640 GT	Arizona 640 XT	Arizona 660 GT
Arizona 660 XT	Arizona 1260 GT	Arizona 1260 XT

Arizona 1280GT	Arizona 6160 XTS	Arizona 6170 XTS
Arizona 2260 XT	Arizona 2280XT	Arizona 2200 series
Arizona 1280 XT	Arizona 2280 GT	Arizona 6100 series
Arizona 2260 GT		

Replacement UV inkjet lamps for Oce printers include:

Subzero 055A	Subzero 085H	3010105468
3010108581	3012000243	3010109681
3010111639	3010111622	3010109531
3030117500	3010117501	3010109598
3010115952		



Oce—Cannon Arizona printers use two (2) lamps, one on each side of the carriage. To reduce gloss banding and maintain equal UV dosage, replace both UV lamps at the same time. Additionally, we recommend replacing lamp housing air filters during bulb change procedure.

Finally, during lamp changeover, always inspect the quartz plate for signs of misting ink or dust.



We manufacture quartz plates for most Océ – Cannon Arizona printers. Typical part number includes 3010107066. Price is reasonable and quality exceeds OEM component thanks to our use of GE USA quartz.